



FIG. 2





FIG. 3

SERVICE-AFFECTING LINE-LEVEL ALARMS - EQUIPMENT
UNIT FAIL
IMPROPER REMOVAL
LINE LEVEL ALARMS
SERVICE—AFFECTING LINE—LEVEL ALARMS — FACILITY
LINE AIS
B2 SIGNAL DEGRADE
LOF
LOS
OPTICAL OUTPUT FAILURE
RFI
SPAN SWITCH FAIL



FIG. 4a










FIG. 5a

